

ProTech GII, TPS, and MSM User Configuration Guidance

Issue

ProTech GII, TPS, and MSM controls support a variety of configuration options. When using Active speed probe sensors, certain configurations could lead to a lapse in overspeed protection, if multiple faults occur in the system comprised of the ProTech, field wiring and speed sensors.

Description

The ProTech GII, TPS and MSM are fault tolerant safety control devices that are fully configured by customers for each unique site application. These products have many functional options available and the system is designed to continually provide its primary function, even when **one** fault occurs anywhere in the ProTech system.

It has come to our attention that some user configurations of these products, may not react as expected when a **second** fault occurs in the ProTech system.

These safety products are all configurable by the user, so it is important to emphasize the following points:


- On any configurable device it is possible to have a valid configuration that may not do all
 that is expected, verification of customer and installers requirements and unit testing at site
 commissioning is required to ensure the appropriate response to faults in the system.
- On any fault tolerant system, a single fault should be investigated and addressed. Depending
 on the configuration, running the system in a prolonged mode with an active alarm, leaves it
 in a state where a second fault could cause a trip or prevent the unit from performing its
 primary function.

If your configuration settings utilize one of the following features, this Service Bulletin can be disregarded:

1. Probe Type: PASSIVE (such as MPU's)


2. Speed Fail Trip: USED


Configure Speed Input				
Probe Type		PASSIVE		
Nr of Gear Teeth		60		
Gear Ratio		1.0000		
Overspeed Trip		4100.0 RPM		0
Sudden Speed Loss		TRIP		
Speed Loss Threshold		200.0 RPM		
Press ENTER to edit value				
Monitor Menu	View Logs	Config Menu	Test Menu	



Service Bulletin 01671 p.2

If your configuration settings are using Active probes (not MPU's) and your configuration has Speed Fail Trip set to "NOT USED" follow the instructions in the Corrective Action section below.





Affected Units

All units shipped with the following part numbers:

GII	TPS	MSM
8237-1244	8237-1248	8237-1252
8237-1245	8237-1249	8237-1253
8237-1246	8237-1250	8237-1254
8237-1247	8237-1251	8237-1255
8237-1367	8237-1371	8237-1375
8237-1368	8237-1372	8237-1376
8237-1369	8237-1373	8237-1377
8237-1370	8237-1374	8237-1378
8237-1594	8237-1602	8237-1492
8237-1595	8237-1603	8237-1493
8237-1596	8237-1604	8237-1494
8237-1597	8237-1605	8237-1495
8237-1598	8237-1606	8237-1496
8237-1599	8237-1607	8237-1497
8237-1600	8237-1608	8237-1498
8237-1601	8237-1609	8237-1499
8237-1660	8237-2602	8237-2492
8237-2594	8237-2603	8237-2493
8237-2595	8237-2604	8237-2494
8237-2596	8237-2605	8237-2495
8237-2597	8237-2606	8237-2496
8237-2598	8237-2607	8237-2497
8237-2599	8237-2608	8237-2498
8237-2600	8237-2609	8237-2499
8237-2601	8237-2614	


Potentially affected ProTech units may have also shipped as sub-components of other Woodward cabinets, kits and systems. Specific customer sales order details are provided by the appropriate Woodward Customer Service Representative.

Service Bulletin 01671 p.3


Corrective Action

If you are currently using configurations described above then at your earliest convenience, plan to modify your unit configuration with the following recommendations.

It is recommended that on ProTech GII products, the option Speed Fail Trip always be set to "USED" whenever the configuration of the speed input probe type is "Active".



It is recommended that on ProTech TPS or MSM products, the option Speed Fail Trip always be set to "Used" whenever the configuration of the speed input probe type is "Active". If this is not desired, due to a need to have other Safety Instrumented Functions (SIF) protected in all 3 kernels, then use the "Speed Redundancy Management" option and configure both "Base Function" and "Fallback Function" to be HSS.



Service Bulletin 01671 p.4

Customer Action

To review their ProTech configuration and compare it with the information in this bulletin to see if any of these potential problem conditions are possible.

We suggest that customers with units that are currently in operation, to verify that they are not running with active module alarm conditions that could lead to a potential issue.

Copyright © Woodward, Inc. 2020 All Rights Reserved



PO Box 1519, Fort Collins CO 80522-1519, USA 1041 Woodward Dr, Fort Collins CO 80524, USA Phone +1 (970) 482-5811

Email and Website—www.woodward.com

Woodward has company-owned plants, subsidiaries, and branches, as well as authorized distributors and other authorized service and sales facilities throughout the world.

Complete address / phone / fax / email information for all locations is available on our website.