

MicroNet™ Analog Combo Module Speed Sensing

MicroNet™ Analog Combo Module Speed Sensing

General

In a case where the MicroNet™ Analog Combo module has a ground fault (non-isolated common on one or more of its input or output dc commons), a high level of noise induced into these dc commons has caused the module's speed-sensing circuitry to intermittently sense erroneous speed levels.

Recommendations per the Manual

- Correct the system and module-related wiring ground fault condition.



Do not connect chassis ground or PE ground to signal common.

From:

MicroNet Simplex Digital Control, MicroNet Plus Digital Control, manual
26166V2 (Revision H) Section
15.2.6.1—Shields and Grounding


—or—

MicroNet TMR® Digital Control manual 26167V2 (Revision New) Section
13.2.4—Shields and Grounding

- Addresses sources of noise.
Refer to:
MicroNet Simplex Digital Control, MicroNet Plus Digital Control, manual
26166V2 (Revision H) Section
15.2—Installation Procedures
—or—
MicroNet TMR Digital Control manual 26167V2 (Revision New) Section
13.2—Installation Procedures
- Installing a wire jumper across any unused MPU or Prox speed input terminals will improve the Analog Combo module's immunity to high levels of noise.

IMPORTANT

When a speed sensor input channel has been wired as either MPU or proximity probe input, the unused MPU/Prox must be jumpered at the FTM. When an input channel is not used, both the MPU and Prox inputs must be jumpered.



From:
 MicroNet Simplex Digital Control, MicroNet™ Plus Digital Control, manual 26166V1 (Revision G) Section 9.5, Figure 9-16
 –or–
 MicroNet TMR Digital Control manual 26167V1 (Revision B) Section 7.7, Figure 7-27

If you have any question about the issue explained above, please contact one of Woodward's facilities and refer to this application sheet number.



Revisions

This publication may have been revised or updated since this copy was produced. To verify that you have the latest revision, check manual **26311**, *Revision Status & Distribution Restrictions of Woodward Technical Publications*, on the *publications page* of the Woodward website:

www.woodward.com/publications

The latest version of most publications is available on the *publications page*. If your publication is not there, please contact your customer service representative to get the latest copy.

We appreciate your comments about the content of our publications.

Send comments to: icinfo@woodward.com

Please reference publication **51314**.



PO Box 1519, Fort Collins CO 80522-1519, USA
1000 East Drake Road, Fort Collins CO 80525, USA
Phone +1 (970) 482-5811 • Fax +1 (970) 498-3058

Email and Website—www.woodward.com

Woodward has company-owned plants, subsidiaries, and branches,
as well as authorized distributors and other authorized service and sales facilities throughout the world.

Complete address / phone / fax / email information for all locations is available on our website.